

# **SL Creek Tree Management**

**Update on May 23, 2013 Tree Assessment Study  
Notice to Residents**


**Kwablah Attiogbe**

**Alameda County Flood Control and Water  
Conservation District  
Environmental Program Manager**

# San Leandro Creek

## Tree Assessment Study is

- on District owned properties between UPRR to Hwy 580 with several hundreds of trees.



# The Tree Assessment Study

- will evaluate

- Structural integrity of trees
- Map location of each tree using GPS

- And Provide the basis for:

**Developing Comprehensive Tree Management Plan &  
Tree Risk Assessment & Maintenance for Public Safety**





# **2011 Tree Hazard Reduction 3 Locations**

- **Held Community meetings**

# SAN LEANDRO CREEK TREE MANAGEMENT

1. HUFF AVE
2. CAREY /HASS
3. ST. MARY AVE




# RECENT EFFORTS MANAGEMENT EFFORT

<b>TREES</b>	<b>TOTAL</b>	<b>CAREY AVE</b>	<b>HUFF AVE</b>	<b>ST MARY</b>
Prune	15	4	1	10
Remove	17	8	4	5
Coppice	2	N	2	0



# Trees were Prune to Maintain Aesthetics



## Disturbed Bank Restored Beautifully



## Habitat improved with New Native Trees



**END**

**END**

# Implemented Site Improvement Measures

- **KEPT EXISTING NATIVE TREE SEEDLINGS**
- **USED FELLED TREE LOGS TO SECURE TOE OF SLOPE**
- **PLANTED NEW FAST GROWING TREES**
- **REMOVED IVIES FROM TREES**